

Original post set 1821 by Wm. B. Laughlin with witnesses: 7" sugar maple S 83 W 19 links, 7 beech N 62 12 links per Marion County Atlas pg. 4. There is no reference to this corner in the Pike Township Legal Survey Book. Reference (no date) called for stone, ties supplied by Hendricks County Surveyor, called railroad spike over stone 7-20-77. Excavated corner 7-28-87 found stone 7" down. Set Harrison. Re-tied 3-10-2000 by Wilcoxen.

1.1	0	70	70	OI	2
- 11		12	32	1) ?	5

REF.	DISTANCE	DESCRIPTION				
3841 6	fl ====					
1.	72,19	Sw corner of ADDRESS 6206 brick 4'up				
2.	79.35'	Southerly corner of ADDRESS 6206 4'up				
3,	93,64'	Southerly corner of ADDRESS 6206 4'up				
4.	102.81	SE corner of ADDRESs 6206 4'up				
5.	172.48'	Due E to stone in hole off road				
6.	44.47					
	Note: Co	rner paved over. Nail set by Will Johnson. Checked &				
	verified	. Called Will Johnson with N-S & E-W distances				
		nail to where coords put the corner.				